



**REPAIR INSTRUCTIONS  
GROB G 103**

»TWIN II «

N8485W

s/n 3250

Utah Soaring Association

Manufactured by:  
Burkhart Grob Flugzeugbau  
8939 Mattsies  
Flugplatz Mindelheim-Mattsies  
West Germany  
Telefon 0 82 68 / 4 11  
Telex 539 623

## INDEX

	Page
1 Forword	1
2 Authorized Materials and Suppliers	2
3 Simplified "Texture" plan	4
4 Repair of GFK material	5
5 Damage to section of GFK foam-sandwich	6
6 Damage to section of GFK Styropor-sandwich	8
7 Damage to section of GFK laminate	8
8 Paint-work	8
9 Repair of Metal Fittings	10
10 Major Repairs	10
11 Construction details of extra equipment attachment fittings	11
12 Maintenance of Breaksystem	12

### 1. Forword

The Glider "TWIN II" is constructed from Glass-Fibre reinforced Plastic (GFK). The fuselage consist of GFK laminate. The load bearing surfaces (wings) and the Tailplane consist of GFK laminate with a foam supporting layer (GFK foam-sandwich). The Tail-fin and control surfaces consists of GFK styropor sandwich.

December 1980

## 2. Authorized materials and suppliers

**Resin:** Shell Glycidäther 162 (Epikote 162)

**Hardener:** BASF Laromin C 260

**Mixing:** 100 parts Resin - 38 parts Hardener

Ratio by weight

### Glass Fibre Cloth

Supplier: Interglas Textil GmbH, Söflinger Str. 246, 7900 Ulm

Use	Cloth	Weight g/qm	Interglas- Nr.
Fuselage	Double Twill	161	92 110
	Double Twill	390	92 140
	Chain Reinforced	433	92 146
Wings	Double Twill	161	92 110
	Double Twill	276	92 125
	Chain Reinforced	433	92 146
Elevator, Rudder and Ailerons	Double Twill	276	92 125
	Double Twill	161	92 110

All Glass-Fibre cloth is Alcholine free. E Glass with Votan-A-Finish or Finish I.550.

### Rovings:

EC 10-80-2400 K 43

Supplier:

Gevetex  
4000 Düsseldorf  
Postfach 1205

### Foam Material

PVC-Hartschaum  
Conticell 60  
8 and 8 mm large  
Spec. Weight 60 kg/m<sup>3</sup>

Continental AG  
3000 Hannover

**Styropor:**

Thermopete  
4 mm large  
Spec. Weight 15 kg/m<sup>3</sup>

Poron-Werke GmbH  
6122 Erbach  
Brunnenstraße 5

Depron  
3 mm large  
Spec. Weight 15 kg/m<sup>3</sup>

Firma Kalle  
6202 Wiesbaden/Bibrich

**Filling Material for Resin**

Microballoons Brown

Lackfabrik Bäder KG  
7300 Eßlingen  
Schließfach 25

Cotton Flock  
Type FL 1 f

Schwarzwälder Textil-Werke  
7623 Schenkenzell  
Postfach 12

**Paint**

PE-Schwabbellack  
White. No. 03-69120  
UP-Hardener No. 07-20510  
100 Schwabbellack Paint (Gel-Coat)  
3 Hardener mix ratio by Weight.  
Thinners No. 06-30260

Lesonal-Werke  
7000 Stuttgart 30  
Postfach 30 07 09

**Red Paint**

Nitro-Cellulose-Kombilack  
Blood-Orange RAL 2002

Lackfabrik Bäder KG  
7300 Eßlingen  
Schließfach 25

December 1980

### 3. Simplified "Texture" plan


Reinforced regions for special loads and stress conducting are not shown.

#### 1. Flügel

Außenlaminat  
1 Lage 92 110 längs  
1 Lage 92 125 längs  
Kern  
Corticell 60 8 mm  
Innenlaminat  
1 Lage 92 125 diagonal

#### Wing

Outer laminate  
1 Layer 92 110 lengths  
1 Layer 92 125 lengths  
Core  
Corticell 60 8 mm  
Inner laminate  
1 Layer 92 125 diagonal



#### 2. Rumpf

Von außen nach innen  
1 Lage 92 110 längs  
1 Lage 92 148 längs  
3 Lagen 92 140 diagonal

#### Fuselage

From outside to inside  
1 Layer 92 110 lengths  
1 Layer 92 148 lengths  
3 Layers 92 140 diagonal



December 1980



**3. Ruder**


Höhenruder oben  
Querruder oben  
Seitenruder rechts und links

1 Lage 92 110 diagonal  
1 Lage 92 125 diagonal  
Kern Depron 3 mm  
1 Lage 92 110 diagonal

**Controls**

Elevator above  
Aileron above  
Rudder left and right

1 Layer 92 110 diagonal  
1 Layer 92 125 diagonal  
Core Depron 3 mm  
1 Layer 92 110 diagonal



Höhenruder unten  
Querruder unten  
2 Lagen 92 125 diagonal


Elevator below  
Aileron below  
2 Layers 92 125 diagonal

**4. Höhenflosse**

2 Lagen 92 110 diagonal  
Kern: Conticell 60 8 mm  
1 Lage 92 110 diagonal

**Fin**

2 Layers 92 110 diagonal  
Core: Conticell 60 8 mm  
1 Layer 92 110 diagonal



December 1980

#### 4. Repair of GFK material

If the glider is damaged, first examine the outer surface very carefully, frequently other structural parts are involved, fractures can run unseen under the outer surface.

Carry-out repairs with extreme care. As the outer surface of GFK gliders is stressed (loading bearing), failure of this skin can lead to structural failure.

Keep to the Resin-Hardening mixing ratio exactly = 0.5% using a clean mixing pot. The ratio of Glass fibre — to Resin mix is approximately 1 to 1. Grind or splice the repair, before laying damp laminate on it, so that dirt cannot penetrate and stop safe adhesion.

As in plywood, the direction of the fibre glass cloth lay (length or diagonal) is of extreme importance to its strength. It is necessary to know approximately how many fibre and their direction in the damaged part with reference to the simplified texture plan, so it may be restored to the correct wall strength. If a small piece of the damaged laminate is broken off and burnt, the remaining glass-fibres can be counted and identified.

Splicing and grinding are time consuming, to save trouble, grind only as much away as necessary, only to the size of the cloth patch. When it is necessary to shorten the repair time it may be done with a hot air blower to speed the resin hardening time.

**Warning.** A too high temperature will produce large air bubbles in the cloth. A tent can be built out of foil, through which hot air can be guided, and thereby avoiding local overheating. In making repairs to control surfaces, be careful not to increase their weight as there is danger of reating flutter conditions.

#### 5. Damage to section GFK Foam-Sandwich (GFK Hard-Foam-Sandwich)

It can appear that only the outer surface (the outside laminate) is damaged but it can also happen that the whole skin (outside and inside hard foam laminate) is destroyed.

##### a) Important

With a split or fracture, the laminate can become detached from the supporting foam. Start by removing loose laminate until firm laminate is reached. To remove the foam laminate use a grinding disk, grinding block or sharp knife. With a grinding block or sharp knife only remove the cloth around the damage. Splice ratio per cloth covering approximately 20 mm ratio laminate thickness to splice: approximately 1:50.



After grinding out the splice, the repair must be thoroughly cleaned. Remove the dirt (also out of the foam pores) with compressed air. Wash the splice with carbon tetrachloride or Acetone, in case it has been contaminated with dirt or grease.

Fill up the pores of the foam with Resin and Microballoons until it is smooth. Then join the laminates with the correct cloth, laying it in the right direction.

Repairs must be dirt and grease free. (Figure 1)

At room temperature the resin will harden in about 8 hours.

The repair can now be ground smooth and be painted.

**Warning:** Grind only to the edge of the repair.

#### **b) Damage to the whole of the Sandwich**

When the inner laminate is destroyed, so there is no binding with the foam, widen the hole so far as foam material is secure, then it is possible to repair the inner laminate. A edge of at least 20 mm must be obtained (retaining laminates thickness : splice ratio approximately 1:50).

The inner laminate must be carefully ground and cleaned.

The outer laminate is repaired as described in section a). (Figure 2)

With „minor“ damage a piece of thin plywood support can be glued with Pattex from within on the inner skin, the cloth patch of the inner laminate can then be layed in and the hole filled with resin and Microballoons mixed with Styroporballs. When hardened (ca. 8 hours room temperature) the outer surface can be ground smooth and the outer cloth put on.

The plywood support should remain as part of the repair. When the hole is of large or of long size the plywood support should be held in place with thin nails which can be removed later, by pushing them out from the top surface.

**Warning:** The plywood support must be well jointed to avoid wrinkles in the cloth. (Figure 3)

With large holes in the sandwich, the weight of the Microballoons filler must be considered. A piece of Conticell hard foam is made before-hand, which exactly fits into the existing hole. The inside pores are closed with resin and Microballoons and laid on the inner cloth to harden, until the foam is just bendable (evtl. hot air). Then the foam with



enthickened resin (cotton flock-Microballoons) can be glued in the hole. Microballoons are used to close the outside pores, the repair is then ground and the outside cloth is then laid on.

## 6. Damage to section of GFK Styropor-Sandwich

Repair of Styropor damage of section.

The Styropor has a closed upper surface, the cloth is held with pure or lightly thickened resin. Splits in the upper surface pores can be filled. With large damage put a patch inside and allow to harden first before working further. This will stop the structure wrinkling.

**Warning:** Do not use strong heat to speed up hardening time, or Styropor will develop blisters and the repair must be done again.

## 7. Damage to section of GFK Laminate

Repairs to GFK laminate are simple. Splice the laminate around the hole, lay the cloth in layers on (largest patch first) and after 2-3 hours, when the resin has partially hardened smooth over with resin and Microballoons. Splice length pro cloth layer ca. 20 mm. Retaining laminate thickness : Splice ratio 1:50. In case the splice is dirty it can be cleaned with Carbon Tetrochloride or Acetone.

With large damage a under laying support (plywood) should be used. Wet laminate should not bridge a gap of more than 20 mm unsupported. The plywood support can be held in place with Pattex glue and nails (e. g. metal fitting in fuselage) which can be removed afterwards. (Figure 4).

## 8. Paint-work


As soon as the laminate of the repaired section is hard, it can be rough ground with (80 grit) sandpaper. Large unevenness must be filled and smoothed with white polyester filler. Then with fine dry-grinding paper (150 grit) until a moderately smooth outer surface is produced. Before painting, the repaired section must be perfectly cleaned from grinding dust, separated mediums and other foreign bodies.

For successful painting, with Gel-Coat (Schwabbellack + hardener) a not too large brush should be used, putting on several thin coats, until the laminate can no longer be seen.

The first coat should be allowed to harden and then ground with

1 Lage 92 110  
1 Layer 92 110

1 Lage 92 125  
1 Layer 92 125



Kern  
Core  
Conticell 60

Microballoons

Abb. 1  
Fig. 1





Abb. 2  
Fig. 2

Außengewebe  
outer cloth



Dünnes Sperrholz  
Thin plywood

Microballoons  
+ Styroporkugeln  
Styropor balls

Abb. 3  
Fig. 3

Rumpfschale  
Fuselage skin

1 Lage 92 146  
1 Layer 92 146

1 Lage 92 110  
1 Layer 92 110

3 Lagen 92 140  
3 Layers 92 140




Abb. 4  
Fig. 4

(360 grit wet paper) additional coats should then be added and likewise ground.

The final finish should be carried out with 600 grit or 800 grit Wet and Dry grinding paper and then polished with a silicon-free car polish or with hard-wax, using a polishing machine.

## 9. Repair of Metal Fittings

### a) Damage to Steel Fittings

Repair of damage to fittings made of steel should only be accomplished after approved procedures are obtained from the manufacturer.

Welded steel fitting (push rods) out of 1.7734.4 or 1.0308.1 (St. 35.4). Welding only to be carried out with WIG Welding method (Wolfram-Inert-Gasschmelzschweißung) and with welding material 1.7734.2 (for 1.7734.4) and 1.7324.0 (for 1.0308.0 or combination of 1.7734.4 and 1.0308.1)

### b) Damage to Aluminium Castings

Repair of Aluminium castings 3.2374.6 (GALSi7 Mgwa) cannot be carried out. Fractured or bent Aluminium castings must be replaced by new ones.

**Warning:** Bent or chipped Aluminium castings are not under any circumstances to be straightened.

### c) Main Wing and Fuselage fittings

The main fitting between wing and fuselage (4x in the fuselage) 7 steel balls (ø 6 mm) have contained in each fitting. The balls are forced by a sliding cover through the lock shell into a groove in the moveable lateral axis force bolts in the spar caps thus securing the wings.

Faults of one or more balls, the connecting fitting should be changed.

## 10. Major repairs

Major repairs are only to be carried out by the manufacturer or by an agent (who has the authorization of the manufacturer.).

Major repairs are:

December 1980



- Broken off wing, fuselage, tailplane, control surface, spar stumps (spar caps)
- Ripped or torn-out - Main fittings (In fuselage  $\varnothing$  55 x 3, Fitting of the tailplane in fin. In the wing, aileron securing both  $\varnothing$  24 mm, joining bearing GE 25. Spar cap bolts  $\varnothing$  25 mm).
- Destruction of main rib (vertical frame)
- Damage to the GFK laminate (tear, splits, cracks immediately near the main fittings).

### 11. Construction details of extra equipment attachment fittings

The fittings for the oxygen bottles are built in as standard on the right side of the luggage compartment. Bearing stands and quick action lock can be obtained from the manufacturer.

Other fitting points can be installed by the owner. (Figure 5)




Abb. 5  
Fig. 5

The fitting must be made as shown in the drawing so as to take the weight of the additional equipment. Fittings made in this manner must stand a load 10 g without failure.

When additional equipment is fitted the glider must be re-weighed to see whether the C of G is within the permitted limits.

Blueprints for the installation of radio and oxygen equipment are obtainable from the manufacture.




## 11. Maintenance of Breaksystem

When dismantling the Mainwheel for cleaning or greasing purposes, or changing the tire, unscrew Poly-stop nuts M8 and remove wheelaxle to the left. Then remove distance pipe (p 42x2) to the right. (distance bush = Distanzbüchse). Remove wheel downwards, clean all parts and grease before assemble again.

### Chainging of breakshoes

- a) Remove the wheelcover.
- b) Loosen 1/4 inch screws (spanner size 11 mm) to take out break. Do not remove breakpipe or you have to bleed again.
- c) Take off the two parts, on witch the breaklining are riveted on.
- d) Mount new breaklining with rivets, assemble in reverse order.
- e) Shape of breaklining.



66-30  
M1:1

### Bleeding of breaksystem

- a) Mount transparent plasticpipe on bleedingscrew put other end of pipe in a container with breakfluid.
- b) Loosen bleading screw, when break via leaver and breakzylinder pushes breakfluid trough the brake.
- c) Bleeding is complete when no more airbubbles can be seen in transparent plastic pipe.

Remarks:

The breakfluid DOT 3 (ambercoloured) is available in every shop for car parts. Standardized within Europe.

The mainbreakzylinder with reservoir, is under the baggagcompertment.

December 1980

---